

REPLACEMENT SEPARATORS

INGERSOLL RAND - contd.

| O.E.M. # | P.S.I. PART # | LIST PRICE |
|----------|---------------|------------|
| 92754696 | CEIR610P | 239.25 |
| 92765783 | CEIR1219 | 442.10 |
| 92785328 | CEIR1919P | 1,169.18 |
| 92808286 | CEIR57P | 214.24 |
| 92824473 | CEIR38 | 139.27 |
| 92866508 | CEIR412P | 210.69 |
| 92890334 | CEIR59BP | 217.83 |
| 93188019 | CEIR1213P | 398.25 |

INTERVAC

| O.E.M. # | P.S.I. PART # | LIST PRICE |
|-----------|---------------|------------|
| 67004-000 | CEIV1224P | 617.47 |
| 67005 | CEIV1924P | 1,260.52 |
| 67007-000 | CEIV67P | 224.97 |
| 67009 | CEIV814P | 303.52 |
| 5171 | CEIV816P | 321.36 |

JOY-SULLIVAN

| O.E.M. # | P.S.I. PART # | LIST PRICE |
|-----------------|---------------|------------|
| 5017945 | CEJ710PU | 282.33 |
| 5017945-1 | CEJ715PU | 312.22 |
| 5017945-2 | CEJ69P | 192.82 |
| 5017945-4 | CEJ1424C | 584.59 |
| 5017945-5 | CEJ1414 | 438.44 |
| 5018000-001 | CEJ88P | 264.23 |
| 5018000-002 | CEJ610H | 204.41 |
| 5018000-003 | CEJ816P | 317.80 |
| 5018000-008 | CEJ1414P | 602.86 |
| 5018000-009 | CEJ1424AP | 873.23 |
| 5018000-010 | CEJ816AP | 339.23 |
| 5018000-013 | CEJ1924P | 1,245.91 |
| 5018000-014/004 | CEJ1424BP | 858.62 |
| 5018000-016 | CEJ1436P | 931.69 |
| 5018000-019 | CEJ1414BP | 602.86 |
| 5019210 | CEJ830 | 346.37 |
| 543117-01 | CEJ610 | 178.53 |
| 543117-02 | CEJ84 | 178.53 |
| 543117-03 | CEJ85 | 210.69 |
| 543117-04 | CEJ104 | 282.10 |
| 543117-05 | CEJ106 | 282.10 |
| 543117-07 | CEJ815 | 260.67 |
| 543117-08 | CEJ818 | 271.37 |
| 543117-09 | CEJ820D | 310.66 |
| 543117-10 | CEJ1415A | 434.79 |
| 543117-11 | CEJ1418A | 507.86 |
| 543117-12 | CEJ1425 | 617.47 |
| 543117-13 | CEJ1430A | 573.63 |
| 543117-14 | CEJ108 | 303.52 |
| 543117-16 | CEJ1026 | 471.33 |
| 543117-17 | CEJ617 | 196.40 |
| 543117-18 | CEJ1424BP | 858.62 |
| 543117-19 | CEJ824 | 307.08 |
| 543117-20 | CEJ1024 | 385.63 |